

From
Dr. S.Lakshmi Priya,
Assistant Director,
Dept of Geology and Mining,
Coimbatore - 641 018.

To
The Member Secretary,
Coimbatore Local Planning Authority,
Tatabad,
Coimbatore.

K.Dis.No. 1484 / Mines/2017 Dated 19.02.2018

Sir,

Sub : Geo Technical Report – Department of Geology and Mining – Coimbatore District – Coimbatore North Taluk – Gudalur village and Town Panchayat – NOC requested by the Secretary, Sri Ramakrishna Mission Vidyalaya, Periyanaickenpalayam, Coimbatore – for regularization of already constructed buildings within the campus - in S.F.Nos.46,47,48,49,50/1,54,55/1,55/2,56,57,58,59,60,61,62,63,64, 65/1,65/2,66,67,69/3,69/4,69/5,69/6,70/1,70/4,71/1,71/2,72,73,74/3, 78/1A, 78/1B, 90,91, 92,93/1, 93/2,107/1, 107/2,108, 109(part), 110, 111, 112,113,114 - Area fall under hill Taluk – report sent – reg.

Ref : .The Secretary, Sri Ramakrishna Mission Vidyalaya, Periyanaickenpalayam, Coimbatore letter dated 18.09.2017

I invite kind attention to the references cited, wherein the Secretary, Sri Ramakrishna Mission Vidyalaya, Periyanaickenpalayam, Coimbatore has requested the Dept. of Geology & Mining to furnish the NOC for regularization of already constructed buildings within the campus in S.F.Nos. 46,47,48,49,50/1,54,55/1,55/2,56,57,58,59,60,61,62, 63, 64, 65/1, 65/2, 66,67,69/3, 69/4, 69/5,69/6,70/1,70/4,71/1,71/2,72,73,74/3,78/1A, 78/1B, 90, 91, 92, 93/1, 93/2, 107/1,107/2,108,109(part),110,111,112,113,114 of Gudalur village, Coimbatore North Taluk as the area comes under the purview of HACA.

LOCATION

The area is located within the Sri Ramakrishna Mission Vidyalaya, Periyanaickenpalayam campus on the Western and Eastern sides of Coimbatore – Mettupalayam road at Periyanaickenpalayam.

SLOPE

The area for the already constructed building within the Sri Ramakrishna Mission Vidyalaya, Periyanaickenpalayam campus is a plain land.

SOIL THICKNESS

On examination of the area it is revealed that the clay soil is noticed for a depth of 4 to 6 meters.

LAND USE PATTERN

The area is surrounded with buildings on all sides


DRAINAGE

There is no stream course passing within the campu.

RECOMMENDATION

The area applied by the Secretary, Sri Ramakrishna Mission Vidyalaya, Periyanaickenpalayam for regularization of already constructed buildings within the campus in S.F.Nos. 46, 47, 48, 49, 50/1, 54, 55/1, 55/2, 56, 57, 58, 59,60,61,62, 63, 64, 65/1, 65/2, 66,67,69/3,69/4, 69/5, 69/6, 70/1, 70/4, 71/1, 71/2, 72, 73, 74/3,78/1A, 78/1B, 90, 91, 92, 93/1, 93/2, 107/1, 107/2, 108, 109(part),110, 111, 112, 113,114 of Gudalur village, Coimbatore North Taluk is a plain land and Geo technically stable. Therefore it is recommended for the regularization of already constructed buildings within the campus of Sri Ramakrishna Mission Vidyalaya, Periyanaickenpalayam subject to the following conditions.

1. In future, construction activities should be carried out only after obtaining proper permission from the HACA.
2. There should not be any disturbance for the nearby streams and natural flow of water.
3. Proper drainage facility should be provided.
4. Eco system and green atmosphere should be developed by growing number of trees within the premises.
- 5.No hindrance shall be caused to adjoining lands.
6. Proper safety distance should be provided for the National Highway road


Assistant Director,
Dept. of Geology and Mining,
Coimbatore.


19/12/18